



Power Systems

1400 East South Blvd • Montgomery, AL 36116
(334) 286-8551 • (334) 286-8018 Fax
<http://www.kellyaerospace.com>

Service Information Letter

Bulletin No. A-109

Issue Date: September 17, 2002

200F SERIES FUEL PUMP REPLACEMENT NOTIFICATION

Kelly Aerospace Inc has determined the potential exists for fuel seepage around the rear cover of the following 200F Series fuel pump serial numbers:

<u>Serial Number:</u>	<u>Part Number:</u>
FEN001FP	200F-5002
FEN002FP	200F-5002
FEN003FP	200F-5002
FEN004FP	200F-5002
FEN005FP	200F-5002
FEN006FP	200F-5002
FEN009FP	200F-5002
FEN010FP	200F-5002
FEN012FP	200F-5002
FEN014FP	200F-5002
FEN016FP	200F-5002
FEN017FP	200F-5002
FEN018FP	200F-5002
FEN019FP	200F-5002
FEN020FP	200F-5002
FFN002FP	200F-5002
FFN020FP	200F-5002
FEN022FP	200F-5003
FEN032FP	200F-5004
FFN032FP	200F-5004

To address this potential Kelly Aerospace issues this Service Information Letter to inform the customer of the need for immediate, mandatory, replacement of these fuel pumps with a unit manufactured after August 1, 2002.

For questions concerning any issues related to this matter please contact Kelly Aerospace, Technical Services Department at 334-227-8306.