



2900 Selma Highway
Montgomery, AL 36108 USA
Tel: 334-386-5400 Fax: 334-386-5450
<http://www.hartzell.aero>

Service Letter

Service Letter No. 056

Fuel Pump - Spare Parts Release HET P/N 202F-1001 & 202F-1002

1. Planning Information

A. Effectivity

- (1) Lycoming Engines, Inc. model AEIO-540-D4D5 aircraft engine utilizing Lear-Romec P/N RG9570K1 or RG9570K1/M Fuel Pump. All engine serial numbers.
- (2) Lycoming Engines, Inc. model AEIO-540-D4D5 aircraft engine utilizing a Lycoming P/N 62E22586 Fuel Pump. All engine serial numbers.
- (3) Beechcraft models 56TC, A56TC, 60, A60, and B60 aircraft utilizing a Beechcraft P/N 50-389141-1 Fuel Pump. Applicable aircraft serial numbers.
- (4) Lycoming Engines, Inc. model TIO-540-S1AD aircraft engine utilizing Lear-Romec P/N RG9570P1 or RG9570P1/M Fuel Pump. All engine serial numbers.
- (5) Lycoming Engines, Inc. model TIO-540-S1AD aircraft engine utilizing a Lycoming P/N 62E22585 or LW-19012 Fuel Pump. All engine serial numbers.

B. Reason

- (1) Hartzell Engine Technologies LLC is issuing this Service Letter as a notice that an FAA PMA has been obtained for the P/N 202F-1001 and 202F-1002 Fuel Pumps.
- (2) Fuel Pump HET P/N 202F-1001 and 202F-1002 may be obtained through approved HET distributors.

C. Description

- (1) This publication provides Additional Maintenance Information (AMI).
- (2) Fuel Pump HET P/N 202F-1001 is now an approved replacement for Lear-Romec P/N RG9570K1 or RG9570K1/M and Lycoming P/N 62E22586 Fuel Pump used on the AEIO-540-D4D5 aircraft engine.
- (3) Fuel Pump HET P/N 202F-1001 is now an approved replacement for Beechcraft P/N 50-389141-1 Fuel Pump used on Beechcraft models 56TC, A56TC, 60, A60, and B60 aircraft.
- (4) Fuel Pump HET P/N 202F-1002 is now an approved replacement for Lear-Romec P/N RG9570P1, RG9570P1/M, Lycoming P/N 62E22585 and LW-19012 Fuel Pumps used on the TIO-540-S1AD aircraft engine.

Service Letter

Service Letter No. 053

Fuel Pump - Spare Parts Release HET P/N 202F-1001 & 202F-1002

D. Approval

- (1) This technical publication has been approved by Hartzell Engine Technologies LLC.

E. Other Publications Affected

- (1) None

F. References

- (1) FAA PMA No. PQ1383CE Supplement No. 16.
- (2) Applicable aircraft/engine maintenance manual.
- (3) HET P/N 200201-0000 Rev. F or later (ICA).
- (4) HET PMA Eligibility found at <http://www.hartzell.aero/pma/>

2. Material Information*

- (A) One (1) each, Fuel Pump, HET P/N 202F-1001 as desired for maintenance. This HET Fuel Pump is available through any HET distributor.
- (B) One (1) each, Fuel Pump, HET P/N 202F-1002 as desired for maintenance. This HET Fuel Pump is available through any HET distributor.

* Miscellaneous parts, including fittings and mounting hardware, must be obtained from the engine manufacturer through its approved distribution system.

3. Contact Information

- A. Contact HET Product Support for all communications regarding the technical content of this Service Letter.

- (1) Phone +1.334.386.5400
- (2) Fax +1.334.386.5450
- (3) E-mail at techsupport@HartzellEngineTech.com
- (4) Address:

Hartzell Engine Technologies LLC
2900 Selma Highway,
Montgomery, AL 36108, USA.