



2900 Selma Highway
Montgomery, AL 36108 USA
Tel: 334-386-5400 Fax: 334-386-5450

Service Letter

Service Letter No. 048 Rev. 1

201F Fuel Pump Seal, Bearing, & Pump Housing Part Supersedure

TRANSMITTAL SHEET

This page transmits the revision of Service Letter 048 Rev. New to Service Letter 048 Rev. 1, dated July 7, 2014.

- Revision SB 048 Rev. New, dated January 15/14
- Revision SB 048 Rev. 1, dated July 7/14

HET approval has been obtained on technical data in this publication that affects type design.

Changes are shown by a change bar in the left or right margins coinciding with the change in the affected page.

This revision is issued to change the following:

- Remove service information that has been incorporated into the component maintenance manual.

Service Letter

Service Letter No. 048 Rev. 1

201F Fuel Pump Seal, Bearing, & Pump Housing Part Supersedure

INTENTIONALLY LEFT BLANK



2900 Selma Highway
Montgomery, AL 36108 USA
Tel: 334-386-5400 Fax: 334-386-5450

Service Letter

Service Letter No. 048 Rev. 1

201F Fuel Pump Seal, Bearing, & Pump Housing Part Supersedure

1. Planning Information

A. Effectivity

- (1) All Hartzell Engine Technologies LLC (HET) model 201F fuel pumps of any part number, are affected by this Service Letter (SL). The affected fuel pumps are FAA/PMA approved.

WARNING: DO NOT USE OBSOLETE OR OUTDATED INFORMATION. PERFORM ALL INSPECTIONS OR WORK IN ACCORDANCE WITH THE MOST RECENT REVISION OF THE APPLICABLE ENGINE AND/OR AIRCRAFT MAINTENANCE MANUAL (MM) AND THIS SERVICE LETTER (SL). INFORMATION CONTAINED IN THE MM AND THE SL MAY BE SIGNIFICANTLY CHANGED FROM EARLIER REVISIONS. USE OF OBSOLETE INFORMATION MAY CREATE AN UNSAFE CONDITION THAT MAY RESULT IN DEATH, SERIOUS BODILY INJURY, AND/OR SUBSTANTIAL PROPERTY DAMAGE. REFER TO THE APPLICABLE MM INDEX AND THE HET WEBSITE FOR THE MOST RECENT REVISION LEVELS.

B. Concurrent Requirements

- (1) None.

C. Reason

- (1) The P/N 70F-0008 seal, P/N 75F-0002 bearing, and P/N 30F-0004 pump housing are no longer available for the 201F fuel pump and have been superseded by P/N 70F-0011 seal, P/N 75F-0008 bearing, and P/N 30F-0011 pump housing.
- (2) To delete redundant installation and inspection criteria from service letter SL 048 Rev. New.
- (3) To announce that installation and inspection criteria for use of superseded part numbers has now been incorporated in the HET P/N 200201-0000 Fuel Pump Overhaul & Maintenance manual, Revision E (or later).

D. Description

- (1) This publication provides Additional Maintenance Information (AMI).
- (2) This Service Letter provides notification that P/N 70F-0008 seal, P/N 75F-0002 bearing, and P/N 30F-0004 pump housing are no longer available for the 201F fuel pump and have been superseded by P/N 70F-0011 seal, P/N 75F-0008 bearing, and P/N 30F-0011 pump housing.

Service Letter

Service Letter No. 048 Rev. 1

201F Fuel Pump Seal, Bearing, & Pump Housing Part Supersedure

E. Approval

(1) This technical publication has been approved by Hartzell Engine Technologies LLC.

F. Manpower

(1) Not applicable.

G. References

(1) HET P/N 200201-0000 Fuel Pump Overhaul & Maintenance manual Rev. E or later.

H. Other Publications Affected

(1) Not applicable.

2. Material Required*

<u>A. Original HET P/N</u>	<u>Description</u>	<u>Replacement HET P/N</u>
70F-0008	Seal, pump	70F-0011
75F-0002	Bearing, pump	75F-0008
30F-0004	Housing, pump	30F-0011

* Additional parts may be required to complete overhaul or repair activities.

3. Contact Information

A. Contact HET Product Support for all communications regarding the technical content of this Service Letter.

(1) Phone +1.334.386.5441

(2) Fax +1.334.386.5410.

(3) E-mail at techsupport@HartzellEngineTech.com.

(4) Address

Hartzell Engine Technologies
LLC 2900 Selma Highway,
Montgomery, AL 36108, USA.